



RAM AIRCRAFT, LP

7505 Karl May Drive • Waco Regional Airport • P.O. Box 5219 • Waco, TX 76708
Phone: (254) 752-8381 • Fax: (254) 752-3307 • www.ramaircraft.com

ENGINES • PARTS • PROPELLERS • ACCESSORIES • STC'S

TSIO-520-EB Cessna 402B and Cessna T310/320

RAM OHE Continental TSIO-520-EB Engine

- Horsepower - 300 hp
- TBO - 1400
- RAM *Nickel New* Cylinders - NE
- Crankcase - heavy w/ 7th studs - OHE
- Crankshaft - OHE
- Camshaft - RAM High Efficiency
- Starter and starter drive - OHE
- Spark plugs - new
- Magneto harness - Champion - new
- Magnetos - Champion Slick 6320 - NE [pressurized]
- Fuel injection system - OHE
- Oil filter - new
- Induction couplings intake manifold - new
- Metal baffles - refurbished and painted - exchange
- Baffle seals - RAM *SureStand* red silicone rubber - new
- Oil cooler: Flushed and inspected - exchange
- Air/oil separator - inspected and repaired - exchange
- Balance - crankshaft and rod sets - exchange
- Core Return Policy - See: RAM Exchange Core Policy on Page 2.

• Also see:
[RAM Value Options & Compliance Items.](#)

OHE = Overhauled Exchange
NE = New Exchange - OEM or PMA
New = New Outright - OEM or PMA
New Items = Subject to test time, ferry time and inventory time.

Kit Components - Packaged Separately and Included

- Hoses - intake manifold to throttle body - new
- Coupler - throttle body to turbo - new
- Throttle and control assembly - OHE
- Turbocharger - OHE
- Turbo controller - OHE
- Overboost relief valve - OHE
- Air filter - RAM - new
- Spare accessory gasket set - new

RAM OHE Engine CMI TSIO-520-EB: \$44,437

Shipped - exchange, or Custom Overhauled - exchange

Additional Specifications

- **RAM Overhauled Engine TBO Warranty:**
100% Engine and accessories for the 1st year, or 500-hrs, whichever occurs first. Thereafter, the engine only is warranted on a prorata basis to TBO at RAM's reduced minimum accrual rate of only 30 hours per month, thus extending coverage over four years. For complete details go to www.ramaircraft.com/ramtbowarranty
- **Exchange Core Policy:** Engine, crankcase, crankshaft, internal gears, exhaust, accessories, propeller, governor, and hardware items are only sold on an exchange basis, based upon the customer's exchange of like type and normal runout cores as removed from subject aircraft, and serviceable to RAM's overhaul specifications. Cores should be returned within 30 days of RAM OHE engine shipment, or immediately with a RAM installation. Non-serviceable core fees will be due and payable to RAM.
- **Items not included:** Vacuum pump, alternator, tach generator, hoses, wastegate, exhaust risers and exhaust parts are not included unless specified by a RAM Work Order Supplement.
- **Crankcase Upgrade:** RAM overhauls engines using only heavy crankcases. Upgrade light exchanged core crankcase to heavy crankcase. Ask your RAM Sales Consultant for current prices.
- **Crankshaft Upgrade:** RAM only uses large diameter VAR crankshafts. If the exchanged core crankshaft is not a large diameter VAR crankshaft additional upgrade charges apply. Ask your RAM Sales Consultant for current prices.
- **Please see:**
[RAM Value Options and Compliance Items.](#)
[RAM TSIO-520 Engine Overhaul Specifications with Exchange Engine Core Policy.](#)

Optional Parts and Engine Installation Items

- **Wastegate and actuator** - Each - OHE: \$1,679 [Core Charge: \$275]
- **Engine shock mounts** - Engine Set of (4) - new: \$1,028
- **Exhaust slip joint** - w /hardware - each - RAM PMA new: \$325
- **Exhaust risers** - Stainless steel - Engine Set - PMA new: \$1,460
[two per engine \$730 per side]
- **Fuel & Oil - Primary Hose Kit** - *Teflon™* w/ integral firesleeve
Engine set - new: ...402B: \$1,278 ...T310 / 320: \$1,356
- **Propeller unfeathering accumulator** - Source for contaminating the engine oil supply. RAM recommends older accumulator be disabled unless replaced by a newer unit. Each - OHE: \$875 [Core Charge: \$400]
- **Engine control cables** - throttle, prop, mixture, alternate air, and cowl flaps - Each - RAM PMA new: Call
- **RAM Parts Catalog** - Additional engine & installation parts. Ask for a free copy.
- **Upgrade** from standard massive plugs to fine wire spark plugs. Per engine - new: \$923
- **New 24v, 100 amp Alternator Package** for airplanes with existing 100 amp alternators: Hartzell Engine Technologies ALV9610 with nut, thrust washer, cotter key, and New PMA Alternator clutch. When purchased with an engine RAM will install for no additional cost. (Retail \$2,444) Only when purchased with a RAM engine: \$1,462 each - Exchange
- **Ask your RAM Representative for details on your alternator options for airplanes with other configurations.**
- **Cooling Shroud Kit** for dry vacuum pump - New: \$55 each

RAM Aircraft, LP • 7505 Karl May Drive • P.O. Box 5219 • Waco, TX 76708
Phone: (254) 752-8381 • Fax: (254) 752-3307 • www.ramaircraft.com

