



# RAM AIRCRAFT, LP

7505 Karl May Drive • Waco Regional Airport • P.O. Box 5219 • Waco, TX 76708  
 Phone: (254) 752-8381 • Fax: (254) 752-3307 • www.ramaircraft.com

**ENGINES • PARTS • PROPELLERS • ACCESSORIES • STC'S**

## IO-550-N Cirrus SR22

### RAM OHE TCM IO-550-N Cirrus SR22 Engine - exchange

- Horsepower: 310 hp
- TBO: 2000 hrs.
- RAM *Nickel New* Cylinders - NE
- Crankcase - Heavy w/ 7th studs - OHE
- Crankshaft - OHE
- Camshaft - RAM
- Starter with relay - NE
- Starter drive - OHE
- Spark plugs - new
- Magneto harness - TCM - new
- Magnetos - TCM - OHE
- Fuel injection system - OHE
- Couplings - Induction Manifold - new
- Inter-cylinder baffles: refurbished and painted - exchange
- Throttle assembly - OHE
- Bracket mount - four or six point - customer specify
- Oil filter - new
- Oil Cooler - (flush, pressure test, inspect, and reuse)
- Balance - crankshaft and rod sets - exchange
- Core Return Policy - See: RAM OHE TCM IO-550-N Engine Overhaul Specifications.

OHE = Overhauled Exchange  
 NE = New Exchange - OEM or PMA  
 New = New Outright - OEM or PMA  
 New Items = Subject to test time, ferry time and inventory time.

### Kit Components - Packaged Separately and Included

- Air Filter - new
- Engine Oil - Break-in oil - new
- Alternator - OHE - Primary only

### RAM OHE Engine TCM IO-550-N: \$34,989

Shipped - exchange, or Custom Overhauled - exchange

## Additional Specifications

- **RAM's TBO Warranty Support Program:**  
100% Engine and Accessories 1st yr, or 350 hrs, whichever occurs first.  
100% Engine only for two (2) yrs or 700 hrs, whichever occurs first.  
Thereafter, the engine only is warranted on a prorata basis to TBO at RAM's reduced minimum accrual rate of only 23 hours per month, thus extending coverage out to seven years.
- **Exchange Core Policy:** Engine, crankcase, crankshaft, internal gears, exhaust, accessories, propeller, governor, and hardware items are only sold on an exchange basis, based upon the customer's exchange of like type and normal runout cores as removed from subject aircraft, and serviceable to RAM's overhaul specifications. Cores should be returned within 30 days of RAM OHE engine shipment, or immediately with a RAM installation. Non-serviceable core fees will be due and payable to RAM.
- **Items not included:** Magneto sensor assembly, secondary alternator, A/C compressor, prop governor, hoses, exhaust risers and exhaust parts are not included unless specified by an optional purchase order and a RAM Work Order Supplement issued at the time of engine order placement.
- **Customer - Discuss the following with your RAM Representative before ordering.**
  - **Aftermarket STCs:** Engine parts and accessories required by aftermarket STCs are not included with a RAM OHE engine.
  - **Aftermarket STC Parts:** Substitution or addition of aftermarket parts is an additional charge. Please review with RAM prior to engine overhaul. Pre-shipment of aftermarket cores may be required.
  - **Fuel System:** To ensure selection of the proper fuel system, customer needs to specify the currently installed TCM engine specification number when placing an engine order.

RAM Aircraft, LP • 7505 Karl May Drive • P.O. Box 5219 • Waco, TX 76708  
Phone: (254) 752-8381 • Fax: (254) 752-3307 • [www.ramaircraft.com](http://www.ramaircraft.com)

